Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	((dc or (direct voltage)) and (inverter or capacitive) and (charging near switch) and control and lever and delay and ((first and second) near shaft) and (tolerance or clearance)). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:03
L2		((dc or (direct voltage)) and (charging near switch) and control and lever and delay and ((first and second) near shaft) and (tolerance or clearance)). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:03
L3		((dc or (direct voltage)) and (charging near switch) and lever and delay and ((first and second) near shaft) and (tolerance or clearance)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:04
L4	1	((dc or (direct voltage)) and ((charge or charging) near switch) and lever and delay and ((first and second) near shaft) and (tolerance or clearance)). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:04
L5	1	((dc or (direct voltage)) and ((charge or charging) near switch) and lever and delay and ((first and second) near shaft)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:11
L6	2	((dc or (direct voltage)) and ((charge or charging) near switch) and lever and delay and shaft).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:05
L7	82	((dc or (direct voltage)) and ((charge or charging) near switch) and lever and delay and shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/14 09:05
L8	2	("4400670" "5619076").PN. OR ("6452469").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/10/14 09:09

			<u>,</u>			
S1	12769	inverter and delay and switch and charging and voltage	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 08:35
S2	229	inverter and delay and (charging near switch) and voltage	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:53
S3	12	inverter and delay and (charging near switch) and voltage and shaft	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:52
S4	58204	"307"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/11 09:52
S5	6	inverter and delay and (charging near switch) and voltage and lever and shaft	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:54
S6	31	delay and (charging near switch) and voltage and lever and shaft	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:54
S7	0	S4 and S6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:54
S8	40	delay and (charging near switch) and voltage and lever	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:56

S9	2	S4 and S8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:54
S10	3384	delay and charging and voltage and lever	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:57
S11	99	S4 and S10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:56
S12	844	inverter and delay and charging and voltage and lever	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 10:00
S13	21	S4 and S12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 09:57
S14	416	capacitive and delay and charging and voltage and lever	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 10:00
S15	16	S4 and S14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/11 10:00
S16	1223	335/59-67.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/11 10:18

S17	358	361/202.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/11 10:18
S18	19	("3325657" "3582732" "3755695" "3784881" "3814948" "3814950" "B451396").PN. OR ("4097791"). URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/10/11 10:21
S19	2225	318/801-803.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	OFF	2007/10/14 08:59

10/14/07 9:18:54 AM C:\Documents and Settings\RBarrera\My Documents\EAST\workspaces\10578332.wsp